


Recall Status Report

95V-202	00 00 34 19 00	Rear brake hose SI#: 2706, 11/2/95, MG 34	1996 R 1100 RT	72
97V-134	00 00 32 06 00	Clutch and hand brake lever adjusting screw SI#: 2791, 8/26/97, MG 32	1998 K 1200 RS	59
97V-237	00 61 02 00 00	Steering lock / ignition switch wiring harness SI#: 2815, 2/23/97, MG 51	R 850 R / R 1100 R	55
98V-258	00 00 16 09 00	Fuel tank to fuel pump gasket SI#: 2863, 1/14/99, MG 16	1998 K 1200 RS	62
Action	00 13 06 00 00	Tech Hold - Fuel distribution unit / install grab handle SI#: 2835 R, 9/28/98, MG 13/46	1999 R 1100 S(A)	97
98V-294	00 00 16 28 00	Fuel distribution unit / secure air tube SI#: 2859, 3/29/99, MG 16	1999 R 1100 S(A)	46
Action	31 42 11 37 00	Check and tighten front trailing arm pinch bolt SI#: 2895R, 6/16/99, MG 31	1999 K 1200 LT	34
Action	00 18 03 00 00	Exhaust canister cannot be cleaned SI#: 2901 R, 12/01/99, MG 18	1998-2000 K 1200 RS	33
Action	46 52 00 77 00	Center stand exchange SI#: 46 002 00 (003) R	2000 K 1200 RS	37
00V-144	00 00 35 00 00	Check and secure rear brake linkage SI#: 34 004 00 (034)	1999 R 1100 S(A)	0
00V-264	00 00 11 15 00 In the process of being issued.	K 1200 RS: Loss of engine oil at oil pump intermediate flange SI# TBD	1998 - 2000 K 1200 RS models	0
00V-266	00 00 11 14 00 In the process of being issued.	K 1200 RS: Loss of coolant at the cylinder head SI# TBD	1998 K 1200 RS models	0
00V-267	00 00 16 11 00	F 650 GS(A) / Dakar fuel tank replacement SI# 16 002 00 (036)	2001 F 650 GS(A) / Dakar models	0

Sincerely,



Thomas J. Plucinsky
Aftersales Manager
BMW Motorcycles



Pat Raymond
Service Logistics Manager
BMW Motorcycles