Service-Information

Group: 34 BRAKES	February 1983	Bulletin No.: 34 004 83 (2071)

- For U.S.A. and Canada Only -

RE: Bleeding Rear Disc Brake on BMW R100RS and R100RT

Dear Dealer:

In some cases, it has proved impossible to bleed the rear disc brake completely.

You are recommended to detach the rear brake caliper and to position it temporarily so that the bleed screw is at the highest point on the brake system, and points upwards. This will ensure full bleeding.

Note:

To prevent the pistons from emerging from the brake caliper during bleeding, insert a board 5 mm (0.2 in) thick between the brake pads.

Yours truly,

BMW OF NORTH AMERICA, INC.

H. Neas
National Service Manager

HN/CS

Please route and initial before filing

Service Manager	Parts Manager	Service Writer	Technicians