Service-Information

Group 00 Maintenance and General Instructions	December 1983	Bulletin No. 00 030 83 (2090)

- For U.S.A. and Canada Only -

RE: REPAIR MANUAL FOR R65 - R65LS MODELS
SUPPLEMENTS 2 and 3

Dear Dealer:

Supplements for the above mentioned shop manual will be supplied to your dealership shortly.

All dealers will receive a copy of each supplement for their own use free of charge.

Further copies can be ordered by the usual parts ordering procedures under part number: 01 55 9 798 115 supplement 2
01 57 9 798 027 supplement 3

The blue pages refer only to models from 1981 onwards and should always be inserted as additional pages.

The publication date of supplement 3 is in error. This supplement was recently delivered from the printer.

Sincerely,

BMW OF NORTH AMERICA, INC.

Richard Dampf
National Technical Manager

RD/cs

Please route and initial before filing

Service Manager	Parts Manager	Service Writer	Technicians