

# Service-Information



Group: 36 WHEELS AND TIRES	February 1982	Bulletin No.: 36 013 82 (2044)
-------------------------------	------------------	-----------------------------------

- For U.S.A. and Canada Only -

Re: R65 / R65LS Tires

## 1. R65

Please be advised that a small number of 1981 R65's will arrive in the United States equipped with "S" rated tires, instead of "H" rated tires, or as indicated in the Rider's Manual and brochures.

Please inspect each 1982 R65 carefully prior to delivery to your customer and advise him if the motorcycle is equipped with "S" tires.

The quality of both tires is substantially equivalent, only rated differently:

Up to 97 mph = "S" 180 km  
Up to 113 mph = "H" 210 km

Should the customer desire the "H" tires, an exchange under warranty should be made.

## 2. R65 LS

Due to the newly-designed, patented "composite" wheels on this model or any future models, the Michelin tires are NOT APPROVED for this application.

Due to extremely high air pressure that must be used to mount the Michelin tire correctly, over the 4° upward sloping bead seat taper in the rim design, the inner tube could be damaged, and could fail after a short period of time in operation.

All R65 LS models are being delivered with "H" tires.

Thank you for your cooperation.

Yours truly,

A handwritten signature in dark ink, appearing to read 'Herb Neas', written over a horizontal line.

Herb Neas  
National Service Manager

lk