

# Service Information Motorrad



After Sales  
UX-VS-1 Pfc

Group 32  
Steering

Munich,  
September '96  
32 009 96 (727) En

Domestic and  
export (not for  
USA or Canada)

All models with four-piston brake calipers: leaking front brake master cylinder

**Problem:** Front brake master cylinder leaking at sealing sleeve

**Action:** The master cylinder has been improved, with no change to the part number. To identify the optimised master cylinder, the date stamp 663 or a higher number is stamped on next to the Magura symbol. Introduction on production bikes was in March 1996. The central parts store in Dingolfing only supplies the new version; parts manufactured earlier have been converted and marked with the **663** date stamp or higher.

**Installation:** When installing a new brake master cylinder, grease the thrust rod with Optimoly MP3; see sketch.

**Part number:** 07 55 - 9 062 476 Optimoly MP 3, 100 g tube

**Sketch:**

