

Service-Information Motorcycle



Group: 3

April, 1992

BMW NA
Service Department

Equipment
Advice

XIX/92
(2519)


For USA Only

Special tool R100R and K75 series (Showa forks)

In order to reassemble the front fork (Showa) the guide bushing must be driven into the fork leg. The special tool illustrated below enables the technician to accomplish this task as well as installing the fork seal.

This tool will be sent to all dealers as per our Automatic Tool Shipment program. The cost of the tool will be charged to your parts account.

- 88 88 6 313 650 - Special arbor



Very truly yours,

BMW of North America, Inc.

Frank Stevens
National Service Manager
Motorcycle Group

Richard Dampf
National Technical Manager

FS:tb/4.5

Please initial and route to the following before filing				
Service	Parts	Sales	Warranty	Technicians