Service-Information Motorcycle



Group: 13

BMW of N.A. Service Department August 1984

Fuel Supply & Adjustments

13 007 84 (2120)

For USA and Canada Only

Modifications to the Intake System on R80GS, R80ST and R80RT Models

As a means of optimizing the part-load power characteristic on these models and reducing fuel consumption, the intake system has been modified and the following new parts incorporated:

- Carburetor

Left: Bing V 64/32/351 Part No. 13 11 1 337 811
Right: Bing V 64/32/352 Part No. 13 11 1 337 812
Technical data as follows:

Main jet 135 Needle jet 2.66

Needle position 3rd notch from top

Idle jet 45 Slide advance 7.5

If complaints are received on motorcycles already delivered, the following converstion can be introduced as a remedy: (However, not through warranty.)

- 1. Replace one intake pipe in the cover of the air cleaner housing with a pipe having an internal cross-section at the intake orifice of 30 x 19 mm. Part No. 13 72 1 337 501
- Installation of Size 135 main carburetor jets Part No. 13 11 1 256 612.

Sincerely,

BMW OF NORTH AMERICA, INC.

Richard Dampf

National Technical Manager

Motorcycle Group

RD/cl