

# Service-Information Motorcycle



BMW NA  
Service Department

Group: 00  
Maintenance &  
General Hints

December 1990  
00 68 90  
(2441)

For USA Only

## New Analog Clock - 1991 Boxer Models

**Information:** The Analog Clock, which has been used on Boxer motorcycles since 1977, has slight modifications for 1991:

1. The most noticeable is the deletion of the second hand.
2. The adjustor knob is in the same position. However, you need only push in on the knob and the minute and hour hands will rotate electrically.

Please pass this information on to your Sales Department so that when they describe the motorcycle functions to a prospective owner, this can be demonstrated.

Very truly yours,

BMW of North America, Inc.

Frank Stevens  
National Service Manager  
Motorcycle Group

Richard Dampf  
National Technical Manager

FS:jel/192.21

Please initial and route to the following before filing				
Service	Parts	Sales	Warranty	Technicians