

Service-Information Motorcycle



BMW NA
Service Department

Group: 00
Maintenance &
General Hints

May, 1992
00 080 92
(2522)

For USA Only

Missing Saddle Bag Locks - 1992 R100RS

Some R100RS's were shipped with the incorrect number of lock tumbler's, or no lock tumbler's at all for the saddle bags.

If you find that a motorcycle which you received is missing these tumbler's, call your Dealer Service Specialist at 1-800-642-9253, with the VIN and numbers of the tumbler's you need.

They will be shipped immediately.

You will have to code the lock tumbler's using the ignition key.

Please refer to Service Information 46 024 89 (2385).

Very truly yours,

BMW of North America, Inc.

Frank Stevens
National Service Manager
Motorcycle Group

Richard Dampf
National Technical Manager

FS:tb/12.5

Please initial and route to the following before filing					
Service	Parts	Sales	Warranty	Technicians	