00 General Information October 1993 00 093 93 (2610) Page 1 of 1

## ALL MODEL BMW MOTORCYCLES

Do not operate the starter motor with the ge	earbox ground disconnected
--	----------------------------

On motorcycles that have additional accessories such as alarms and/or police equipment installed, care must be taken when doing any repair/service work because of additional ground connections at the battery negative terminal.

Some work requires the battery negative terminal be disconnected. If this is done at the gearbox, the accessory ground wires attached at the battery negative terminal can be over looked. If the ignition is switched to on the dash lights will illuminate, and if the starter button is pressed the starter motor will work because a ground path can be found through the accessories -- causing a high AMP/H draw--damaging the accessory and melting the wires in the main wiring harness.

the main willing harriess.
This information came from contact with technicians on the 800 technical assistance line.
We thank you for the input.
BMW of North America, Inc.

Joe Wagner National Service Manager Motorcycle Group Dan Browning National Technical/Training Manager Motorcycle Group

DB:db DB/SI2610