



BAYERISCHE MOTOREN WERKE
AKTIENGESELLSCHAFT

Rundschreiben der Kundendienst-Abteilung

Circular-Letter of the Service Department
Motorcycle: Rear Wheel Drive Group No. 1/52

Munich, 6/11/52
KVK/Ba/Wi/eb

Dear Sirs,

Subject: Greasing propeller shaft R 25 and R 25/2

We had to note in several cases that on removal of the bell-shaped cover, the threaded ring was loosened too. However, as under certain circumstances a loose threaded ring might cause the driving pinion bearing collar of bevel drive housing to crack, we are kindly asking you to take care that after lubrication of the universal joint the threaded ring be tightened first and only thereupon the bell-shaped cover be fitted.

Yours truly,

BAYERISCHE MOTOREN WERKE
Aktiengesellschaft