



BAYERISCHE MOTOREN WERKE
AKTIENGESELLSCHAFT

Kundendienst-Rundschreiben

Circular-Letter of the Service Department
Motorcycles: Rear Drive Group No. 1/56
(91)

Munich, 22/3/56
Schä/Wf/Wi/Se

Dear Sirs,

Subject:

Fitting of axial oil seal 30 04 187 in bevel drive housing
of the BMW R 26 motorcycle

In order to prevent oil leakages of the bevel drive through the axial oil seal the Radiax bearing 6202 DIN 625 must be fitted in a way that the uninscribed side of the bearing shows to the oil seal (Simmerring).

With the cover of the bevel drive housing being removed the Radiax bearing 6206 remains on the coupling dog of the crown wheel unit (ring gear). No lettering should be seen then on the bearing.

Caution! The shims 30 04 106 apply only at the inner race of the Radiax bearing on the coupling dog hub.

Yours truly,

BAYERISCHE MOTOREN WERKE
Aktiengesellschaft