



# Service-Information

Cust.Serv.-Techn.Office Motorcycles R50/R60/R69S/R27 München, 7. 10. 65  
VKT e/wi/be Group: Springs and shock abs. Nr. 2/65 (224) en.

Re: Seal rings on the front wheel swing arm bearing

Dear Sirs,

The hitherto installed seal rings, Part No. 20 00 331, have in some cases been pushed away from their seat and pressed out of the swing when lubricating at high pressures.

New seal rings with a metal capsule are installed as standard equipment, by which measure a pressing-out is avoided.

The new seal rings are installed from the following frame numbers:



639 796	(R 50)
627 5 6	(R 60)
679 497	(R 69 S)
383 866	(R 27)

The Part Number remains unchanged.

Very truly yours,  
BAYERISCHE MOTOREN WERKE  
Aktiengesellschaft

ppa.

i.V.

Makowitzki

Delleske

Kennnis genommen	Betriebsleitung	Werkstatt	KD-Annahme	Gewährleistungs- Sachbearbeiter	E-Teildienst	Ablage Betriebsleitung Werkstatt
---------------------	-----------------	-----------	------------	------------------------------------	--------------	-------------------------------------