



BAYERISCHE MOTOREN WERKE
AKTIENGESELLSCHAFT

Rundschreiben der Kundendienst-Abteilung

Circular-Letter of the Service Department
Motorcycle: Engine Group No. 6/52

Munich, 17/12/52
KVK/Ba/Wi/eb

Dear Sirs,

Subject: Clutch centre plates for all models

With respect to crevices produced on clutch linings, we may draw your attention to the following:

Crevices which coincide with one of the slots machined in the clutch centre or friction plate are due to a slight springiness on these slots. This possibility of expansion, however, is necessary in order to permit the clutch centre plate to be engaged smoothly and then to remain in snug contact with the driving plates.

It would not be a good practice to replace a clutch lining for showing such crevices since these will on no account endanger further operation. Therefore we decline to replace under guarantee clutch centre plates showing lining crevices produced at above mentioned slots.

Yours truly,

BAYERISCHE MOTOREN WERKE
Aktiengesellschaft