

Service-Information Motorcycle



©BMW of N.A.
Service Department

Group: 34
Brakes

February 1990
34 021 90
(2395)

For USA Only


Rear Drum Brake Shoes - All Models from 1981 on, except R80G/S

A new part number for asbestos-free brake shoes has been introduced for all rear drum brake models from model year 1981 and onward, with the exception of the R80 G/S (1981 - 1986).

This part number is a kit containing upper and lower brake shoes, 2 brake return springs, and a rubber absorber which can now be installed on the rear return spring in order to reduce the vibration of the spring which causes the squealing noise during braking.

Part Number 34 21 2 310 523

Refer to Service Information bulletins: 34 013 88 (2296) and 34 011 86 (2230) for additional information.



Very truly yours,

BMW of North America, Inc.

Frank Stevens
National Service Manager
Motorcycle Group

Richard Dampf
National Technical Manager

FS:je1/228.7

Please initial and route to the following before filing

Service	Parts	Sales	Warranty	Technicians