

Service-Information



Group: Instruments	December 1981	Bulletin No.: 62 002 81 (2041)
-----------------------	------------------	-----------------------------------

Subject: Motometer Instruments

Dear Dealer:

Any Motometer instruments which fail to function properly within the warranty period should be replaced with a new instrument.

- 1) When the defective unit is replaced, file claim and retain that instrument properly tagged for disposition by the District Service/Parts Manager.
- 2) Inefficient instruments no longer covered under warranty can be repaired very reasonably. The Motometer repair depot is located at:

North Hollywood Speedometer & Clock Co.
Division of Pacific Parts & Instruments
6111 North Lankershim Boulevard
North Hollywood, California 91606

All repaired instruments are guaranteed for six months, and the average repair is limited to approximately two to four days.

All merchandise is returned by North Hollywood Speedometer & Clock via U.P.S., C.O.D., unless an open account has been established with their company.

A handwritten signature in cursive script, appearing to read 'Herb Neas'.

Herb Neas
National Service Manager

HN:lk