Service-Information Motorcycle

Group: 34

June 1991

BMW NA Service Department

Brakes

34 024 91 (2466)

For USA Only



Brake Pipe Recall - Advance Information

BMW of North America, Inc. will announce a Recall which will affect a relatively small number of 1987 and 1988 R8ORT's, R100RT's, and RIOORS's (only 1,123 motorcycles). The VIN range and model years will be described in a subsequent Service Information bulletin and will describe in detail the repair procedures.

You may wish to order, through normal parts channels, the following kit:

Part No. 34 32 9 062 451

Because of the small number of motorcycles involved, please initially order only one or two kits.

Once we are assigned the official Recall number by the National Highway Traffic Safety Administration, we will release additional information to you via a Service Information bulletin and affected customers will be informed by First Class mail.

Very truly yours,

BMW of North America, Inc.

Frank Stevens

National Service Manager

Richard Dampf

National Technical Manager

FS:je1/160.1

Please initial and route to the following before filing				
Service	Parts	Sales	Warranty	Technicians
	 i			