

Service-Information Motorcycle



©BMW of N.A.
Service Department

Group: 00
MAINTENANCE &
GENERAL HINTS

APRIL 1993
00 092 93
(2589)

For USA Only

PRE-DELIVERY INSPECTION - R1100RS MAINTENANCE & GENERAL INFORMATION

The enclosed booklet is to supplement the training manual given to technicians at the New Boxer Training in March and April.

This manual will provide all information to avoid PDI, 600 mile and subsequent inspections.

IMPORTANT NOTE:

The engine oil capacity is incorrect in:

- This Booklet.
- All Training Materials
- Service & Technical Booklet (which comes with each motorcycle).
- Service Data Chart R1100RS.

The correct capacity is:

- Without filter change 3.75 US quart.
- With filter change 4.0 US quart.

Very truly yours,

BMW of North America, Inc.

Joe Wagner
National Service Manager
Motorcycle Group

Richard Dampf
National Technical Manager

JW/kf/502
Enclosure

Please initial and route to the following before filing

Service	Parts	Sales	Warranty	Technicians