



BAYERISCHE MOTOREN WERKE
AKTIENGESELLSCHAFT

Kundendienst-Rundschreiben

*Circular-Letter of the Service Department
Motorcycles: Suspension Group No. 1/55*

*Munich, October 12th 1955
ba/wf/Dr./Se.*

Dear Sirs,

Subject: R 50 - R 69 front wheel bottom link swing fork

In order to avoid a clashing noise of the fork spring, a protective cover 245 1 62 147 04 can be fitted upon the shock absorbers. Before fitting, shock absorber and protective cover must be exempt from grease in order to guarantee a tight fitting. The protective covers are fitted in our serial production on the R 50 model as of frame No. 550 120 and on the R 69 model as of first engine.

For the purpose of preventing a sliding off from the bolt, also in case the silent-bushes in the fixing eyelets of the front wheel bottom link swing parts have become loose, we are using now:

on the model R 50 as of frame No. 552 500, instead of the disks DIN 1440, washers of 26 mm ϕ and 3 mm width, part number 245 1 62 091 04.

Yours truly,

**BAYERISCHE MOTOREN WERKE
Aktiengesellschaft**